

• PRODUCT INTRODUCTION •



PP	PP	
PP	PP 1000000 10000 1000	
PP PP	PP 100000000 10000000 10	
PP	*	
PP 1000 1000	*	
PP	*	
PP	35 10 5)10000000 1000000 1000)	
PP PP	± 12 100000000 100000 10 10000 10	
PP PP	PP 100000000 10000000 10 10000 10000 10	
PP 1000	PP	
PP	PP 10000 2.0*25*25 100000 10000 10000.	
PP 1000 1000	*	
PP 1000 1000	*	
PP/PP	PP 10000 10000	63
	PP 10000000 100000	54
	PP 100000000 100000000	100
	PP 100000 1000	50
	PP 100000 1000	*
	PP 100000 1000000	45.5
	PP 100000 1000	8
PP	2 100000000 1000000000 1000000 / 10000 100000000 10000	
PP 100000 PP	0.08/PP	
PP 10000 10000	20GP	40HQ
PP / PP 10000000	300-350	800-850


• PARTS REFERENCE •



WORKSHOP

PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



• ENGINEERING CASE •

ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design



CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design

MALAYSIA EXHIBITION



DUBAI EXHIBITION

GUANGZHOU CIFF EXHIBITION



SHANGHAI EXHIBITION



CERTIFICATE



CERTIFICATE

Professional office furniture manufacturer which specialized in the design

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 1 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 2 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 3 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 4 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 1 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 2 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 3 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SGS

Test Report No. SGL20190701977 Date: Aug 01, 2019 Page 4 of 2

WISCONSIN FURNITURE CO., LTD.
100-01, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
General test and test results are in accordance with the following requirements.	Pass

Signature for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai Representative

Signature for and on behalf of:
SGS
Shanghai Representative

QR Code

Image of the product being tested:

SHIPPING

A. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

Q4: 1. 2023 年 1 月 1 日 至 2023 年 12 月 31 日

2023 年 1 月 1 日 至 2023 年 12 月 31 日 2023 年 1 月 1 日 至 2023 年 12 月 31 日 :

2023 年 1 月 1 日 至 2023 年 12 月 31 日 :5

2023 年 1 月 1 日 至 2023 年 12 月 31 日 : T/T (30% 2023 年 1 月 1 日 至 2023 年 12 月 31 日 %70 2023 年 1 月 1 日 至 2023 年 12 月 31 日)

2023 年 1 月 1 日 至 2023 年 12 月 31 日 2023 年 1 月 1 日 至 2023 年 12 月 31 日.

CONTACT US



Manager : Rachel

Whatsapp/Wechat:

0086-13590681820



E-mail:

rachel@new-city.cn