

• PRODUCT INTRODUCTION •



□□	□□	
□□□□	□□□□□□□	
□□□□□	PP □□□□	
□□	□□ 50mm□□□□	
□□	85mm□□□□□□□2□□	
□□	2□0mm□□□□□□□□□□	
□□	35 □□□□□□□ 5□□□	
□□□	±12mm□□□□□	
□□	PP □□□□□□□	
□□□□	□□□	
□□	31 0□□□□□ PP□	
□□	*	
□□	*	
□□/□□	□□□	57.5
	□□□	59
	□□□	97-104
	□□□□	46
	□□□□	48
	□□□□	44-51
	□□	5.5
□□	3 □/□	
□□□	0.075/□	
□□□□/□	20GP	40□□
	300-320	900-912

• PARTS REFERENCE •



WORKSHOP

PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



• ENGINEERING CASE •

ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design



CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design

MALAYSIA EXHIBITION



DUBAI EXHIBITION

GUANGZHOU CIFF EXHIBITION



SHANGHAI EXHIBITION



CERTIFICATE



CERTIFICATE

Professional office furniture manufacturer which specialized in the design

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
WENZHOU FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHANGJIANG TOWN,
SHAOXING DISTRICT, GUANGDONG PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 123456
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
General appearance and dimensions	Pass
Material	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shaoxing, China

Signature: [Signature]
Date: [Date]

SGS

SHIPPING

A. □□□□□□□□□□□□

1*40HQ 15-25 2*40HQ 15-35.....

B. EX FOB CIF C&F LC

OUR SERVICE

A.

B. 100%

C

D

E.

.

FAQ

Q1:

A:

Q2:

A:

Q3:

: 100% 5

Q4:

A:

Q5: 00000000

☐: 000000 T/T (☐☐☐ 30% 000000 70% ☐☐)☐

000000000000

CONTACT US



Manager : Rachel

Whatsapp/Wechat:

0086-13590681820



E-mail:

rachel@new-city.cn