

• PRODUCT INTRODUCTION •



□□	□□	
□□□□	□□□□□□□	
□□□□□	PP □□□□	
□□	5 0mm□□□□	
□□	85mm□□□□□□□2□□	
□□	□□□□□□□□□□□□□□3□□	
□□	35 □□□□□□ 5□□□	
□□□	±12mm □□□□□	
□□	□□□PP□PU□□□□□	
□□□□	□□□	
□□	34 0□□□□ pp □□	
□□	*	
□□	*	
□□/□□	□□□	64
	□□□	63
	□□□	96-103
	□□□□	
	□□□□	
	□□□□	
	□□	
□□	2 □/□	
□□□	0□1/□	
□□□□/□	20GP	40□□
	260-280	660-680

• PARTS REFERENCE •



WORKSHOP

PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



• ENGINEERING CASE •

ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design



CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design

MALAYSIA EXHIBITION



DUBAI EXHIBITION

GUANGZHOU CIFF EXHIBITION



SHANGHAI EXHIBITION



CERTIFICATE



CERTIFICATE

Professional office furniture manufacturer which specialized in the design

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WENZHOU FURNITURE CO., LTD.
NO. 62, SHANGHAI ROAD, WENZHOU INDUSTRIAL ZONE, CHINA
SHANGHAI DISTRICT, SHANGHAI, CHINA

The following inspection was carried out and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item No.: 12345
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Overall test and inspection results are satisfactory.	Pass

For further details, please refer to the following report.

Report for and on behalf of:
WENZHOU FURNITURE CO., LTD.
Shanghai District, China

[Signature]
Shanghai District, China

[QR Code]

[Image of Office Chair]

SHIPPING

A. □□□□□□□□□□□□

1*40HQ 15-25 2*40HQ 15-35.....

B. EX FOB CIF C&F LC

OUR SERVICE

A.

B. 100%

C

D

E.

.

FAQ

Q1:

A:

Q2:

A:

Q3:

: 100% 5

Q4:

A:

Q5: 1111111111

1: 11111111 T/T (1111 30% 11111111 70% 1111)

1111111111111111

CONTACT US



Manager : Rachel

Whatsapp/Wechat:

0086-13590681820



E-mail:

rachel@new-city.cn