


● PRODUCT INTRODUCTION ●



□□	□□	
□□□□	□□□□□□□	
□□□□□	□□□□□□□	
□□	35□□□□□□ 5□□□	
□□□	±12mm □□□□□	
□□	□□□□□□	
□□□□	□□□□	
□□	25*25*2□0MM □□□□ □□□□□□□□□□	
□□/□□	□□□	67
	□□□	51
	□□□	99
	□□□□	50
	□□□□	50
	□□□□	46
	□□	9.5
□□	2 □/□	
□□□	0.11/□	
□□□□/□	20GP	40□□
	260-300	580-600


● PARTS REFERENCE ●



WORKSHOP

PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



• ENGINEERING CASE •

ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design



CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design

MALAYSIA EXHIBITION



DUBAI EXHIBITION

GUANGZHOU CIFF EXHIBITION



SHANGHAI EXHIBITION



CERTIFICATE



CERTIFICATE

Professional office furniture manufacturer which specialized in the design

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SGS

Test Report No. SGL-201908010171 Date: Aug 01, 2019 Page 1 of 1

MOORE FURNITURE CO., LTD.
MOORE FURNITURE MANUFACTURING INDUSTRIAL ZONE, CHONGQING TOWN,
SHENYI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: STRENGTH
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
STRENGTH	PASS

Comments: The test results are in accordance with the requirements.

Signature: [Signature] Date: [Date]

SGS
Shanghai Inspection

SHIPPING

A. 0000000000000000

1*40HQ 15-25 2*40HQ 15-35.....

B. EX FOB CIF C&F LC

OUR SERVICE

A.

B. 100%

C

D

E.

.

FAQ

Q1:

A:

Q2:

A:

Q3:

: 100% 5

Q4:

A:

Q5: 1111111111

1: 11111111 T/T (1111 30% 11111111 70% 1111)

1111111111111111

CONTACT US



Manager : Rachel

Whatsapp/Wechat:

0086-13590681820



E-mail:

rachel@new-city.cn