

• PRODUCT INTRODUCTION •

PP With Fibre Glass Armrest Waiting Chair Supplier China

ITEM	DESCRIPTION	
Upholstery	Mesh back & Elastic fabric	
PP structure	PP with fibre glass mesh back.	
Foam	35kgs original foam(5cm)	
Plywood	±12mm plywood seat	
Armrest	PP with fibre glass armrest.	
Lumbar support	Fixed	
Base	25*25*2.0MM with connector Metal chrome frame(inner tube)	
Size/cm	Total Width	65
	Total Depth	60
	Total Height	97
	Seat Width	50
	Seat Depth	50
	Seat Height	45
	Arm Width	4.5
Package	4pcs/ctn	
CBM	0.11/pc	
Loading Qty/pcs	20GP	40HQ
	260-280	710-730

• PARTS REFERENCE •



WORKSHOP

PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



01 Drilling



02 Riveting



03 Robot system



04 Foam sticking



05 Fabric cutting



06 Sewing



07 Nailing



08 Installation



09 Testing



10 Cleaning&packing



11 Fitting packing



12 Packing

• ENGINEERING CASE •

ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design



OUR PHOTOS

CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design

MALAYSIA EXHIBITION



DUBAI EXHIBITION

GUANGZHOU CIFF EXHIBITION



SHANGHAI EXHIBITION



CERTIFICATE



CERTIFICATE

Professional office furniture manufacturer which specialized in the design

SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019


Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SGS

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

WISCONSIN FURNITURE CO., LTD.
NO. 10, SHANGHAI ROAD, SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary

Test Item	Result
12100	Pass

For further details, please refer to the following page(s).

Report for and on behalf of:
WISCONSIN FURNITURE CO., LTD.
Shanghai, China

SGS
Shanghai, China



SHIPPING

A. Depends on your qty and requirement of order ,
15-25 work days for 1*40HQ container, 15-35 days for 2*40HQ and so on.....

B. EX works, FOB shenzhen, CIF, C&F ,LC and so on ,
delivery terms discuss with salesman.

OUR SERVICE

- A. Own complete supply chain.
- B. 100% quality guaranteed.
- C. Reasonable price.
- D. Products are in various style.
- E. Good performance for delivery.
- F. Adequate inventory(components).

Best after-sale service:If it appear any quality complaints and disputes,we will establish of
product information feedback system,establish service files,responsible for the quality of
the accident identified and deal with our client .

FAQ

Q1:Can we have your sample?

A:Sure.Sample are available for each model.They can be ready in 7-15days upon receipt of payment.

Q2:Can you give us discount?

A:Discount is negotiable for large quantity.

Q3:Can you give warranty of your products?

A:Yes,we extend a 100% satisfaction guarantee on all items.We may give the warranty 5 years.

Q4:Are you manufacturer or trading company?

A:We are professional manufacturer for more than 10 years in furniture industry.

Q5:How about the payment terms?

A:We accept advance T/T(30% deposit before produce, 70% balance before delivery),

other requirement pls discuss with salesman.

=====● CONTACT US ●=====



Manager : Rachel

Whatsapp/Wechat:

0086-13590681820



E-mail:

rachel@new-city.cn