

## • PRODUCT INTRODUCTION •

### Best Quality Home Computer Office Visitor Chair

ITEM	DESCRIPTION	
Upholstery	Mesh back & Elastic fabric	
PP structure	PP with glassfibre	
Castor	*	
Gaslift	*	
Mechanism	*	
Foam	35kgs original foam(5cm)	
Plywood	±12mm plywood seat	
Armrest	PP with fibre glass armrest	
Lumbar support	Yes	
Base	25*25*2.0mm metal paint frame.	
Headrest	*	
Seat cover	PP Dustproof seat cover	
Size/cm	Total Width	64
	Total Depth	60
	Total Height	98
	Seat Width	50
	Seat Depth	50
	Seat Height	45
	Arm Width	8
Package	2pcs/ctn	
CBM	0.11/pc	
Loading Qty/pcs	20GP	40HQ
	210-240	600-630

## • PARTS REFERENCE •



WORKSHOP

# PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



## • ENGINEERING CASE •



## ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design





# CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design

## MALAYSIA EXHIBITION



## DUBAI EXHIBITION

## GUANGZHOU CIFF EXHIBITION



## SHANGHAI EXHIBITION



## CERTIFICATE



# CERTIFICATE

Professional office furniture manufacturer which specialized in the design

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

**SGS**

Test Report No. SGL20190701971 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.  
SHANGHAI BRANCH: SHANGHAI INDUSTRIAL ZONE, CHONGMING TOWN,  
SHANGHAI DISTRICT, SHANGHAI PROVINCE, CHINA

The following samples were submitted and identified as stated on label of this document:  
Sample Description: OFFICE CHAIR  
Sample Item No.: 12100  
Country of Origin: CHINA  
Sample Processing Date: Aug 01, 2019  
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
Control test and test results are in accordance with the following requirements.	Pass

For further details, please refer to the following report.

Report for and on behalf of:  
SGS TESTING SERVICES (CHINA) CO., LTD.  
Shanghai Branch

Signature: [Signature]  
Stamp: [Stamp]

Image: [Image of office chair]

SHIPPING

A. Depends on your qty and requirement of order ,

15-25 work days for 1\*40HQ container, 15-35 days for 2\*40HQ and so on.....

B. EX works, FOB shenzhen, CIF, C&F ,LC and so on ,  
delivery terms discuss with salesman.

---

## OUR SERVICE

---

- A. Own complete supply chain.
- B. 100% quality guaranteed.
- C. Reasonable price.
- D. Products are in various style.
- E. Good performance for delivery.
- F. Adequate inventory(components).

Best after-sale service:If it appear any quality complaints and disputes,we will establish of

product information feedback system,establish service files,responsible for the quality of

the accident identified and deal with our client .

---

## FAQ

---

### **Q1:Can we have your sample?**

A:Sure.Sample are available for each model.They can be ready in 7-15days upon receipt of payment.

### **Q2:Can you give us discount?**

A:Discount is negotiable for large quantity.

### **Q3:Can you give warranty of your products?**

A:Yes,we extend a 100% satisfaction guarantee on all items.We may give the warranty 5 years.

**Q4:Are you manufacturer or trading company?**

A:We are professional manufacturer for more than 10 years in furniture industry.

**Q5:How about the payment terms?**

A:We accept advance T/T(30% deposit before produce, 70% balance before delivery ),

other requirement pls discuss with salesman.

=====● **CONTACT US** ●=====





Manager : Rachel

**Whatsapp/Wechat:**

0086-13590681820



**E-mail:**

rachel@new-city.cn