

● PRODUCT INTRODUCTION ●

**Fabricante de cadeiras de malha de móveis de escritório  
Foshan China**

ITEM	DESCRIÇÃO	
Estofamento	Costas em malha e tecido elástico	
Estrutura PP	PP com fibra de vidro	
Rodízio	Diâmetro Rodízio de nylon de 50mm	
Elevador de gás	Gaslift preto de 85 mm. (Classe 2)	
Mecanismo	Mecanismo de bloqueio in situ com tensão de inclinação de 2,0 mm	
Espuma	35 kgs de espuma original ( 5cm)	
Madeira compensada	Assento em compensado de $\pm 12$ mm	
Braço	PP com apoio de braço em fibra de vidro	
Apoio lombar	Sim	
Base	31 0mm náilon pé pp	
Encosto de cabeça	Ajustável	
Capa de assento	*	
Tamanho/cm	Largura total	57,5
	Profundidade total	59
	Altura Total	113-120
	Largura do assento	48
	Profundidade do assento	50
	Altura do assento	44-51
	Largura do braço	5.5
Pacote	2 peças/ctn	
CBM	0,086/pc	
Carregando Quantidade/peças	20GP	40HQ
	300-330	780-810


● PARTS REFERENCE ●



WORKSHOP

# PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



## ENGINEERING CASE

# ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design



# CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design



---

## CERTIFICATE

---



# CERTIFICATE

Professional office furniture manufacturer which specialized in the design

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 1 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

The following information was provided by the client and is subject to their responsibility.

Sample Description: OFFICE CHAIR  
 Quantity of Sample: 100PCS  
 Sample Reference No.: OFFICE CHAIR  
 Sample Reference Date: Aug 16, 2018  
 Test Reference Date: Aug 16, 2018 to Aug 17, 2018

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 2 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

Sample: 10101  
 Overall Dimension: 770mm x 760mm x 1000-1050mm  
 Wheel Dimension: 50mm x 60mm

**Control and Safety**

**Test Results**

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 3 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**Control and Safety**

**Test Results**

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 4 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**Control and Safety**

**Test Results**

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 1 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

The following information was provided by the client and is subject to their responsibility.

Sample Description: OFFICE CHAIR  
 Quantity of Sample: 100PCS  
 Sample Reference No.: OFFICE CHAIR  
 Sample Reference Date: Aug 16, 2018  
 Test Reference Date: Aug 16, 2018 to Aug 17, 2018

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 2 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

Sample: 10101  
 Overall Dimension: 770mm x 760mm x 1000-1050mm  
 Wheel Dimension: 50mm x 60mm

**Control and Safety**

**Test Results**

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 3 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**Control and Safety**

**Test Results**

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**SGS**

Test Report No. S24110000001017 Date: Aug 21, 2018 Page 4 of 4

SGS TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

**Control and Safety**

**Test Results**

Tested Parameter	Test Result Summary	Pass/Fail
Control and safety (EN ISO 12128)	Control and safety	Pass

Approved for use on behalf of:  
 TEGITA Furniture Co., Ltd.  
 10/F, No. 100, Zhongyuan Road, Xixiang, Xixiang, Shenzhen, Guangdong, P.R. China

**SGS** TESTING SERVICES (CHINA) CO., LTD. 9000 SOUTH AVENUE, SUITE 1000, CHICAGO, ILLINOIS 60629, USA  
 SGS TESTING SERVICES (INDONESIA) PT. LTD. JALAN PONDOK REJO, SUKSES, BOGOR, WEST JAVA 16152, INDONESIA

## SHIPPING

A. Depende da sua quantidade e exigência do pedido,

15-25 dias úteis para contêiner de 1\*40HQ, 15-35 dias para 2\*40HQ e assim por diante.....

B. EX funciona, FOB shenzhen, CIF, C&F, LC e assim por diante, termos de entrega discutir com o vendedor.

## OUR SERVICE

- A. Própria cadeia de suprimentos completa.
- B. 100% de qualidade garantida.
- C. Preço razoável.
- D. Os produtos estão em vários estilos.
- E. Bom desempenho para entrega.

Melhor serviço pós-venda: Se aparecer alguma reclamação e disputa de qualidade, estabeleceremos

sistema de feedback de informações do produto, estabelecer arquivos de serviço, responsável pela qualidade de

o acidente identificado e tratar com nosso cliente.

## FAQ

### **Q1:Podemos ter sua amostra?**

R: Claro. Amostras estão disponíveis para cada modelo. Elas podem estar prontas em 7 a 15 dias após o recebimento do pagamento.

### **Q2:Você pode nos dar desconto?**

R: O desconto é negociável para grandes quantidades.

### **Q3:Você pode dar garantia de seus produtos?**

R: Sim, estendemos uma garantia de 100% de satisfação em todos os itens. Podemos dar a garantia de 5 anos.

### **Q4:Você é fabricante ou empresa comercial?**

R: Somos fabricantes profissionais há mais de 10 anos na indústria moveleira.

**Q5: Que tal as condições de pagamento?**

R: Aceitamos adiantamento T/T (depósito de 30% antes da produção, saldo de 70% antes da entrega),

Outros requisitos, por favor, discuta com o vendedor.

—————● CONTACT US ●—————



Manager : Rachel

**Whatsapp/Wechat:**

0086-13590681820



**E-mail:**

rachel@new-city.cn