

• PRODUCT INTRODUCTION •

Стул для посетителей современного дизайна с хромированной рамой Производитель Китай

ЭЛЕМЕНТ	ОПИСАНИЕ	
Обивка	Сетка на спине и эластичная ткань	
Структура ПП	ПП со стекловолокном	
Кастор	*	
Газлифт	*	
Механизм	*	
Мыло	35 кг оригинальной пены(5 см)	
Фанера	Сиденье из фанеры ± 12 мм	
Подлокотник	ПП с подлокотником из стекловолокна	
Поясничная поддержка	Да	
База	Металлическая рамка 25*25*2,0 мм.	
Подголовник	*	
Чехол на сиденье	*	
Размер/см	Общая ширина	63
	Общая глубина	54
	Общая высота	100
	Ширина сиденья	50
	Глубина сиденья	*
	Высота сиденья	45,5
	Ширина руки	8
Упаковка	2 шт/кор	
МУП	0,08/шт.	
Загрузка Кол-во/шт.	20GP	40HQ
	300-350	800-850


• PARTS REFERENCE •



WORKSHOP

PRODUCTION PROCESS

Professional office furniture manufacturer which specialized in the design



• ENGINEERING CASE •

ENGINEERING CASE

Professional office furniture manufacturer which specialized in the design



CUSTOMER PHOTOS

Professional office furniture manufacturer which specialized in the design

MALAYSIA EXHIBITION



DUBAI EXHIBITION

GUANGZHOU CIFF EXHIBITION



SHANGHAI EXHIBITION



CERTIFICATE



CERTIFICATE

Professional office furniture manufacturer which specialized in the design

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SGS

Test Report No. SGL-201907010171 Date: Aug 01, 2019 Page 1 of 1

SGS TESTING SERVICES (CHINA) CO., LTD.
SHANGHAI DISTRICT SHANGHAI CHINA

The following inspection was performed and completed on behalf of the client:

Sample Description: OFFICE CHAIR
Inspection Item: 12100
Country of Origin: CHINA
Sample Processing Date: Aug 01, 2019
Test Processing Date: Aug 01, 2019 to Aug 01, 2019

Test Result Summary	Pass/Fail
1. The sample meets the requirements of the following project:	Pass

Signature for and on behalf of:
SGS TESTING SERVICES (CHINA) CO., LTD.
Shanghai

Signature for and on behalf of:
TECITA
Shanghai

Image of the sample:

SHIPPING

A. Зависит от вашего количества и требований к заказу,

15-25 рабочих дней для контейнера 1*40HQ, 15-35 дней для контейнера 2*40HQ и так далее...

в. EX работает, FOB Шэньчжэнь, CIF, C&F, LC и так далее,

Условия доставки обсуждаем с продавцом.

OUR SERVICE

А. Собственная полная цепочка поставок.

Б. 100% гарантированное качество.

С. Разумная цена.

Д. Продукты выполнены в различных стилях.

Е. Хорошая производительность при доставке.

.

Лучшее послепродажное обслуживание: если возникнут какие-либо жалобы и споры по поводу качества, мы организуем

Система обратной связи с информацией о продукте, создание сервисных файлов, ответственность за качество

авария выявлена и разобраться с нашим клиентом.

FAQ

В1: можем ли мы получить ваш образец?

О: Конечно. Образцы доступны для каждой модели. Они могут быть готовы в течение 7-15 дней после получения оплаты.

В2: Можете ли вы предоставить нам скидку?

О: скидка является предметом переговоров для большого количества.

В3: Можете ли вы дать гарантию на свою продукцию?

О: Да, мы предоставляем 100% гарантию на все товары. Мы можем дать гарантию 5 лет.

В4: вы производитель или торговая компания?

О: мы являемся профессиональным производителем более 10 лет в мебельной промышленности.

В5: Как насчет условий оплаты?

О: Мы принимаем авансовый банковский перевод (30% депозит перед производством, 70% баланс перед поставкой),

другие требования, пожалуйста, обсудите с продавцом.

=====● **CONTACT US** ●=====



Manager : Rachel

Whatsapp/Wechat:

0086-13590681820



E-mail:

rachel@new-city.cn